

Service - PDI - Post Service Inspection (Hank) -

HOP081254

Complete

Score	17 / 18 (94.44%)	Flagged items	0	Actions	0
-------	------------------	---------------	---	---------	---

Date of inspection 01/19/2024

Site conducted Unanswered

ALL Machine Serial #'s (Compressor, Engine and Trailer) HOP081254

Trailer :199695
 Compressor:AIA1886887
 Engine :PE6068R048678

Take Pictures of Compressor data plate



Photo 1

Aftercooled? No

Water Separator? Yes

Take Picture of Engine data plate




Photo 2

Engine Tier? Tier 4

Take Picture of Engine Emission Tag



Photo 3

Take Picture of Trailer data plate




Photo 4



Photo 5

Take Picture of controller turned on showing hours



Photo 6

Location

4484c Genoa Red Bluff Rd
Houston TX 77505
United States
(29.633004645883272,
-95.12611297147757)

Any damage to outside machine?

Pass

Take Photo of front of unit



Photo 7

Take photo of drivers side profile



Photo 8



Photo 9

Take photo of drivers side profile with doors open



Photo 10



Photo 11

Take photo of rear of unit



Photo 12

Take photo of passenger side profile



Photo 13



Photo 14

Take photo of passenger side profile with doors open



Photo 15



Photo 16

Photos of door latches and handles - do they work/were they replaced?

Yes



Photo 17




Photo 18



Photo 19



Photo 20




Photo 21



Photo 22




Photo 23



Photo 24

IF NO PAINT - please ensure any residual sticker residue is removed

Yes

Any leaks present?

Pass

Does machine start & Run ok?

Yes

Test ran for 1 hour if under 750 cfm? Test ran for 3 hours if over 750 cfm?

Yes

Take photos of element



Photo 25

Take photos of cooler and fan drive



Photo 26



Photo 27

Take photos of undercarriage



Photo 28

Take photos of engine




Photo 29




Photo 30

Inspect all tank caps (Fuel, DEF, Coolant, etc...)

Yes

Radiator/coolers and top tank in good condition?

Yes

1000 Hour Service Completed

Yes

Oil Stop Valve Rebuilt

Yes

Unload Valve Rebuilt

Yes

Hours recorded on filters from service?

Yes

Service timers reset?

Yes

Controller inspected and functioning properly?


Yes

Battery replaced?


Yes

Battery tie downs in place?

Yes

All harnesses secured?	Yes
Belts replaced, fan, pulley inspected?	Yes
Brakes checked and functioning?	Yes
All Trailer Lights Functioning?	Yes
Wheel bearings greased and no rust?	Yes
Are Hitch and Safety Chains Operational and/or in good shape?	Yes
Jack straightened and welds in good shape?	Yes
	
Photo 31	
Tires within DOT Spec?	Yes
No open Service Bulletins?	Yes
Is outbound OK to book in TMS?	OK to Book in TMS
Service center completing?	LaPorte

Prepared by



Byron hooker
19 Jan 2024 15:55 EST

Video Walkaround during unit test run

[38D66F9C-9397-4F32-883B-BBE2DC35EEC4-video.mov](https://example.com/38D66F9C-9397-4F32-883B-BBE2DC35EEC4-video.mov)

Media summary



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9



Photo 10



Photo 11



Photo 12



Photo 13



Photo 14



Photo 15



Photo 16



Photo 17



Photo 18



Photo 19



Photo 20



Photo 21



Photo 22



Photo 23



Photo 24



Photo 25



Photo 26



Photo 27



Photo 28



Photo 29




Photo 30



Photo 31

File summary

[38D66F9C-9397-4F32-883B-BBE2DC35EEC4-video.mov](#)