

Service - PDI - Post Service Inspection (Hank) -

HOP081262 XAS 750 (Compressor #26794 , Engine # R539835 , Trailer# 199615)

Complete

Score	17 / 18 (94.44%)	Flagged items	0	Actions	0
--------------	------------------	----------------------	---	----------------	---

Date of inspection 11/22/2023

Site conducted Unanswered

ALL Machine Serial #'s (Compressor, Engine and Trailer) HOP081262 XAS 750 (Compressor #26794 , Engine # R539835 , Trailer# 199615)

Take Pictures of Compressor data plate



Photo 1

Aftercooled? No

Water Separator? Yes

Take Picture of Engine data plate




Photo 2

Engine Tier? iT4

Take Picture of Engine Emission Tag




Photo 3




Photo 4

Take Picture of Trailer data plate



Photo 5

Take Picture of controller turned on showing hours



Photo 6

Location

4484c Genoa Red Bluff Rd
Houston TX 77505
United States
(29.632880411246852,
-95.12640088929142)

Any damage to outside machine?

Pass

Take Photo of front of unit



Photo 7

Take photo of drivers side profile



Photo 8

Take photo of drivers side profile with doors open



Photo 9

Take photo of rear of unit



Photo 10

Take photo of passenger side profile



Photo 11

Take photo of passenger side profile with doors open



Photo 12

Photos of door latches and handles - do they work/were they replaced?

Yes



Photo 13




Photo 14




Photo 15



Photo 16




Photo 17




Photo 18

IF NO PAINT - please ensure any residual sticker residue is removed

Yes

Any leaks present?

Pass

Does machine start & Run ok?

Yes

Test ran for 1 hour if under 750 cfm? Test ran for 3 hours if over 750 cfm?

Yes

Take photos of element




Photo 19



Photo 20



Photo 21



Photo 22

Take photos of cooler and fan drive




Photo 23




Photo 24




Photo 25

Take photos of undercarriage



Photo 26



Photo 27



Photo 28




Photo 29

Take photos of engine




Photo 30



Photo 31

Inspect all tank caps (Fuel, DEF, Coolant, etc...)	Yes
Radiator/coolers and top tank in good condition?	Yes
1000 Hour Service Completed	Yes
Oil Stop Valve Rebuilt	Yes
Unload Valve Rebuilt	Yes
Hours recorded on filters from service?	Yes
Service timers reset?	Yes
Controller inspected and functioning properly?	Yes
Battery replaced?	Yes
Battery tie downs in place?	Yes
All harnesses secured?	Yes
Belts replaced, fan, pulley inspected?	Yes
Brakes checked and functioning?	Yes

All Trailer Lights Functioning?	Yes
Wheel bearings greased and no rust?	Yes
Are Hitch and Safety Chains Operational and/or in good shape?	Yes
Jack straightened and welds in good shape?	Yes
 <p>Photo 32</p>	
Tires within DOT Spec?	Yes
No open Service Bulletins?	Yes
Is outbound OK to book in TMS?	OK to Book in TMS
Service center completing?	LaPorte

Prepared by



Earnest Murray
22 Nov 2023 09:24 EST

Video Walkaround during unit test run

[9E8F7F2E-39AF-4A56-8F0C-A9438E57D9C8-video.mov](#)

Media summary



Photo 1




Photo 2




Photo 3




Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9



Photo 10



Photo 11



Photo 12



Photo 13



Photo 14



Photo 15



Photo 16



Photo 17




Photo 18



Photo 19



Photo 20



Photo 21



Photo 22



Photo 23



Photo 24



Photo 25



Photo 26



Photo 27



Photo 28



Photo 29



Photo 30



Photo 31



Photo 32

File summary

[9E8F7F2E-39AF-4A56-8F0C-A9438E57D9C8-video.mov](#)