

Service - PDI - Post Service Inspection (Hank) -

HOP090739 trailer, LDN01476 engine,
AIA 189943 Compressor, one
Compressor missing serial number tag

Complete

Score	18 / 18 (100%)	Flagged items	0	Actions	0
-------	----------------	---------------	---	---------	---

Date of inspection 10/03/2023

Site conducted Unanswered

ALL Machine Serial #'s (Compressor, Engine and Trailer) HOP090739 trailer, LDN01476 engine, AIA 189943 Compressor, one Compressor missing serial number tag

Take Pictures of Compressor data plate



Photo 1

Aftercooled? Yes

Water Separator? Yes

Take Picture of Engine data plate



Photo 2

Engine Tier? T4

Take Picture of Engine Emission Tag



Photo 3

Take Picture of Trailer data plate



Photo 4

Take Picture of controller turned on showing hours



Photo 5

Location

12155 Liberty Dr, Covington, GA
30014, USA
(33.6144256, -83.8279743)

Any damage to outside machine?

Pass

Take Photo of front of unit



Photo 6

Take photo of drivers side profile



Photo 7

Take photo of drivers side profile with doors open



Photo 8

Take photo of rear of unit



Photo 9

Take photo of passenger side profile



Photo 10

Take photo of passenger side profile with doors open



Photo 11

Photos of door latches and handles - do they work/were they replaced?

Yes



Photo 12



Photo 13



Photo 14



Photo 15



Photo 16



Photo 17



Photo 18



Photo 19



Photo 20



Photo 21




Photo 22



Photo 23




Photo 24



Photo 25



Photo 26

IF NO PAINT - please ensure any residual sticker residue is removed

Yes

Any leaks present?

Pass

Does machine start & Run ok?

Yes

Test ran for 1 hour if under 750 cfm? Test ran for 3 hours if over 750 cfm?

Yes

Take photos of element



Photo 27

Take photos of cooler and fan drive




Photo 28




Photo 29




Photo 30

Take photos of undercarriage



Photo 31

Take photos of engine




Photo 32

Inspect all tank caps (Fuel, DEF, Coolant, etc...)

Yes

Radiator/coolers and top tank in good condition?

Yes

1000 Hour Service Completed

Yes

Oil Stop Valve Rebuilt

Yes

Unload Valve Rebuilt


Yes

Hours recorded on filters from service?

Yes

Service timers reset?

Yes

Controller inspected and functioning properly?	Yes
Battery replaced?	Yes
Battery tie downs in place?	Yes
All harnesses secured?	Yes
Belts replaced, fan, pulley inspected?	Yes
Brakes checked and functioning?	Yes
All Trailer Lights Functioning?	Yes
Wheel bearings greased and no rust?	Yes
Are Hitch and Safety Chains Operational and/or in good shape?	Yes
Jack straightened and welds in good shape?	Yes
	
Photo 33	
Tires within DOT Spec?	Yes
No open Service Bulletins?	Yes
Is outbound OK to book in TMS?	NA
Service center completing?	Covington

Prepared by



jerry sommers
3 Oct 2023 10:34 EDT

Video Walkaround during unit test run

[d02c0554-1428-4654-942f-5cdd5d2457cf.mp4](https://example.com/d02c0554-1428-4654-942f-5cdd5d2457cf.mp4)

Media summary



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9



Photo 10



Photo 11



Photo 12



Photo 13



Photo 14



Photo 15



Photo 16



Photo 17



Photo 18



Photo 19



Photo 20



Photo 21



Photo 22



Photo 23



Photo 24



Photo 25



Photo 26



Photo 27



Photo 28



Photo 29



Photo 30



Photo 31



Photo 32



Photo 33

File summary

[d02c0554-1428-4654-942f-5cdd5d2457cf.mp4](#)