

Service - PDI - Post Service Inspection (Hank) -

RRA02136 engine APP218842 Trailer
 AIA1700755 AIA1700756 Compressor

Complete

Score	18 / 18 (100%)	Flagged items	0	Actions	0
--------------	----------------	----------------------	---	----------------	---

Date of inspection 9/13/2023

Site conducted Unanswered

ALL Machine Serial #'s (Compressor, Engine and Trailer) RRA02136 engine APP218842
 Trailer AIA1700755 AIA1700756
 Compressor

Take Pictures of Compressor data plate



Photo 1



Photo 2

Aftercooled? Yes

Water Separator? Yes

Take Picture of Engine data plate



Photo 3

Engine Tier? It4

Take Picture of Engine Emission Tag



Photo 4

Take Picture of Trailer data plate



Photo 5

Take Picture of controller turned on showing hours



Photo 6

Location

12155 Liberty Dr, Covington, GA
30014, USA
(33.6144256, -83.8279743)

Any damage to outside machine?

Pass

Take Photo of front of unit



Photo 7

Take photo of drivers side profile



Photo 8

Take photo of drivers side profile with doors open



Photo 9

Take photo of rear of unit



Photo 10

Take photo of passenger side profile



Photo 11

Take photo of passenger side profile with doors open



Photo 12

Photos of door latches and handles - do they work/were they replaced?

Yes



Photo 13



Photo 14



Photo 15



Photo 16



Photo 17

IF NO PAINT - please ensure any residual sticker residue is removed

Yes

Any leaks present?

Pass

Does machine start & Run ok?

Yes

Test ran for 1 hour if under 750 cfm? Test ran for 3 hours if over 750 cfm?

Yes

Take photos of element



Photo 18

Take photos of cooler and fan drive



Photo 19



Photo 20



Photo 21

Take photos of undercarriage




Photo 22

Take photos of engine



Photo 23

Inspect all tank caps (Fuel, DEF, Coolant, etc...)	Yes
Radiator/coolers and top tank in good condition?	Yes
1000 Hour Service Completed	Yes
Oil Stop Valve Rebuilt	Yes
Unload Valve Rebuilt	Yes
Hours recorded on filters from service?	Yes
Service timers reset?	Yes
Controller inspected and functioning properly?	Yes
Battery replaced?	Yes
Battery tie downs in place?	Yes
All harnesses secured?	Yes
Belts replaced, fan, pulley inspected?	Yes
Brakes checked and functioning?	Yes

All Trailer Lights Functioning?	Yes
Wheel bearings greased and no rust?	Yes
Are Hitch and Safety Chains Operational and/or in good shape?	Yes
Jack straightened and welds in good shape?	Yes
 <p>Photo 24</p>	
Tires within DOT Spec?	Yes
No open Service Bulletins?	Yes
Is outbound OK to book in TMS?	NA
Service center completing?	Covington

Prepared by



jerry sommers
13 Sep 2023 15:40 EDT

Video Walkaround during unit test run

[745ef7c4-10e1-40fb-ab92-fdc939151652.mp4](https://example.com/745ef7c4-10e1-40fb-ab92-fdc939151652.mp4)

Media summary



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9



Photo 10



Photo 11



Photo 12



Photo 13



Photo 14



Photo 15



Photo 16



Photo 17



Photo 18



Photo 19



Photo 20



Photo 21



Photo 22



Photo 23



Photo 24

File summary

[745ef7c4-10e1-40fb-ab92-fdc939151652.mp4](https://www.example.com/745ef7c4-10e1-40fb-ab92-fdc939151652.mp4)