

Service - PDI - Post Service Inspection (Hank) - 950 PD

HOP079022

Complete

Score	19 / 19 (100%)	Flagged items	0	Actions	0
-------	----------------	---------------	---	---------	---

Date of inspection 07/15/24

Site conducted Unanswered

ALL Machine Serial #'s (Compressor, Engine and Trailer) HOP079022

Compressor:AIA2533447
Engine:U003724F

Take Pictures of Compressor data plate



Photo 1

Aftercooled?

Yes

Everything is good




Photo 2



Photo 3

Water Separator?

Yes

Take Picture of Engine data plate



Photo 4

Engine Tier?

Tier4

Take Picture of Engine Emission Tag



Photo 5

Take Picture of Trailer data plate



Photo 6

Take Picture of controller turned on showing hours



Photo 7

Location

4484cGenoa Red Bluff Rd
Houston TX 77505
United States
(29.63290584015511,
-95.12607331082542)

Any damage to outside machine?

Pass

Take Photo of front of unit



Photo 8

Take photo of drivers side profile



Photo 9

Take photo of drivers side profile with doors open



Photo 10

Take photo of rear of unit



Photo 11

Take photo of passenger side profile



Photo 12

Take photo of passenger side profile with doors open



Photo 13

Photos of door latches and handles - do they work/were they replaced?

Yes



Photo 14



Photo 15




Photo 16




Photo 17




Photo 18

Unit Painted and cosmetically repaired? *IF NO PAINT - please ensure any residual sticker residue is removed**

Yes

Any leaks present?

Pass

Does machine start & Run ok?

Yes

Engine health assessment completed? *Please note work required if any

Yes

Everything is good

Perkins Service Bulletin completed?

Yes

Test ran for 1 hour if under 750 cfm? Test ran for 4 hours if over 750 cfm?

Yes

Take photos of element



Photo 19

Take photos of cooler and fan drive



Photo 20



Photo 21

Take photos of undercarriage




Photo 22




Photo 23

Take photos of engine



Photo 24



Photo 25



Photo 26

Inspect all tank caps (Fuel, DEF, Coolant, etc...)

Yes

Radiator/coolers and top tank in good condition?

Yes

1000 Hour Service Completed

Yes

Oil Stop Valve Rebuilt


Yes

Unload Valve Rebuilt

Yes

Hours recorded on filters from service?

Yes

Service timers reset?	Yes
Controller inspected and functioning properly?	Yes
Battery replaced?	Yes
Battery tie downs in place?	Yes
All harnesses secured?	Yes
Belts replaced, fan, pulley inspected?	Yes
Brakes checked and functioning?	Yes
All Trailer Lights Functioning?	Yes
Wheel bearings greased and no rust?	Yes
Are Hitch and Safety Chains Operational and/or in good shape?	Yes
Jack straightened and welds in good shape?	Yes
	
Tires within DOT Spec?	Yes
No open Service Bulletins?	Yes
Is outbound OK to book in TMS?	OK to Book in TMS
Service center completing?	LaPorte

Prepared by



Byron Hooker
15.07.2024 11:45 EDT

Video Walkaround during unit test run

[C7CC6398-5890-4711-A789-83385947476E-video.mov](https://example.com/C7CC6398-5890-4711-A789-83385947476E-video.mov)

Media summary



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9



Photo 10



Photo 11



Photo 12



Photo 13



Photo 14



Photo 15



Photo 16



Photo 17



Photo 18



Photo 19



Photo 20



Photo 21



Photo 22



Photo 23



Photo 24



Photo 25



Photo 26



Photo 27

File summary

[C7CC6398-5890-4711-A789-83385947476E-video.mov](#)